



1-800-331-7617

CURRENT DLP Lamp Cross Reference

UPDATED 20120420

TV BRAND	HOUSING ASSEMBLY	LAMP PART #
Akai	101280603 Type "J"	RP-AKAI
Akai	101280603 Type "Z"	RP-E023
Akai	For TV Model # PT50-DL24	RP-E022-3
Akai	For TV Model # PT61-DL34	RP-E022-1 or RP-E022-3 (CHECK WATTAGE)
Akai	L2114A	RP-AKAI
BenQ	PB7100	RP-E21.8
Bluesky	DLP Replacement Lamp	RP-E023
Brilliant	LCOS Replacement Lamp	Call us.
Domino	HD55	RP-P022
Epson	ELSLP1	RP-P022
Eyevis	DLP Replacement Lamp	RP-E022
Gateway	7005089	RP-E023
Gemstar	DLP Replacement Lamp	RP-E023
HP	L2114-80001	RP-AKAI
HP	TGASF002080A-J	DLPTGASF002080A-J
Hitachi	UX21511	RP-P022
Hitachi	UX21512	RP-P022
Hitachi	UX21513	RP-P022
Hitachi	UX21514	RP-P022
Hitachi	UX21515	RP-P022
Hitachi	UX21516	RP-P022
Hitachi	UX21517	RP-P022
Hitachi	UX21518	RP-P022
Hitachi	UX25951	RP-P022
Infocus	SP50MD10	RP-E21.8
Infocus	SP61MD10	RP-E21.8
Infocus	SP-LAMP-022	RP-E21.8
Infocus	TD61	RP-E21.8
JVC	TS-CL110UAA	RP-P021
JVC	PK-CL120UAA	RP-E19.8

LG	31419SN984A	PR-E022-3
LG	4930V00301	RP-E023
LG	6912B22001A	RP-E021-1
LG	6912B22002C	RP-E023
LG	6912B22007A	RP-E023
LG	6912B22007B	RP-E022
LG	6912B22010A	RP-E022-3
LG	6912V00006C	RP-P022
Loewe	For TV Model : Articos 55HD	RP-E023
Magnavox	31227859084	RP-E023
Mitsubishi	915P016010	No replacement
Mitsubishi	915B455011	RP-E022-4
Mitsubishi	915B403001	RP-E022-4
Mitsubishi	915B441001	RP-E022-4
Mitsubishi	915P020010	RP-E023 (1.3mm)
Mitsubishi	915P020A10	RP-E023 (1.3mm)
Mitsubishi	915P020010-A	RP-E023 (1.3mm)
Mitsubishi	915P026010	RP-E023 (1.3mm)
Mitsubishi	915P026A10	RP-E023 (1.3mm)
Mitsubishi	915P027010	RP-E022-1 <u>May need the removal of housing material (plastic) to accomidate the new lamp.</u>
Mitsubishi	915P027A20	RP-E022
Mitsubishi	915P02A010	RP-E023 (Osram – only)
Mitsubishi	915P028010	RP-P022 (remove corner clips)
Mitsubishi	915P043010	RP-P022-1 (remove corner clips)
Mitsubishi	915P049010	RP-E022-1 Must Remove Filter Material From Housing. Click Here for Instructions
Mitsubishi	915P049A10	RP-E022-1 Must Remove Filter Material From Housing. Click Here for Instructions
		RP-E022-2

Mitsubishi	915P049020	Must Remove Filter Material From Housing.
Mitsubishi	915P061010	Click Here for Instructions RP-E022-2 May need the removal of housing material (plastic) to accomidate the new lamp.
Mitsubishi	WDV-65000LP	RP-P023
Olevia	LCT50HV	RP-P023
Panasonic	TY-LA1000	RP-P022
Panasonic	TY-LA1001	RP-E19.8 (Lamp is sightly smaller, and the retaining bracket needs reworked slightly to secure lamp.)
Panasonic	TY-LA1500	RP-P022
Panasonic	TY-LA2004	RP-E023
Panasonic	TY-LA2005	RP-E023
Panasonic	TY-LA2006	RP-E022-3
Philips	SP.98F01G001	RP-E022-3
Philips	SP.L6502G001	RP-E023
Philips	312243871310	RP-P022
Philips	313912737921	RP-E022-1
Philips	313912877921	RP-E022-3
Philips	928138905390	RP-E022-3
Philips	270, or, 253	RP-P022-1
Philips	228 or 229 or 254 or 266 or 269 or 281	RP-P022
Philips	280	RP-E19.8
Philips	206 or 295	RP-E023
Philips	265 or 283 or 292	RP-E022-3
Philips	250 or 277 or 291 or 297 or 299	RP-E022
Philips	312	RP-P022-2
RCA	260962	RP-E023
RCA	265103, 265103R	RP-E023
RCA	265105	RP-E21.8
RCA	265866	RP-E022
RCA	265919	RP-E022
RCA	269343	RP-E022
RCA	270414	RP-E022
RCA	271326	RP-E022
RCA	275179	RP-E022-3

Sagem	251282989	RP-E023
Sagem	252005505	RP-E023
Samsung	AA47-00003A	RP-E023
Samsung	BP47-00023A	RP-E022-3
Samsung	BP61-00731A	RP-E022 (square) RP-E023 (round)
Samsung	BP96-00224A	RP-E023 Philips
Samsung	BP96-00224 C,D, E, J	RP-E023
Samsung	BP96-00271C	RP-E022
Samsung	BP96-00497A	RP-E022
Samsung	BP96-00608A	RP-E022 (square) RP-E023 (round)
Samsung	BP96-00677A	RP-E022 (square) RP-E023 (round)
Samsung	BP96-00823A	RP-E022 (square) RP-E023 (round)
Samsung	BP96-00826A	RP-E022 (square) RP-E023 (round)
Samsung	BP96-01073A	RP-E022
Samsung	BP96-01074A	RP-E022
Samsung	BP96-01099A	RP-E022-3
Samsung	BP96-01394A	RP-E022
Samsung	BP96-01403A	RP-E022 (square) RP-E023 (round)
Samsung	BP96-01415A	RP-E022
Samsung	BP96-01472A	RP-E022-3
Samsung	BP096-01578A	RP-E022-3
Samsung	BP96-1600A	RP-E022-1
Samsung	BP96-01653A	RP-E022-3
Samsung	BP96-01795A	RP-E022-3
Sharp	ANR65LP1/1	RP-E023
Sharp	ANR65LP2/1	RP-E023-1
Sony	A-1129-776-A	RP-E 19.8
Sony	LMP-S2000	RP-P022
Sony	XL-100 / XL-100E	RP-P023
Sony	XL-2000U	RP-P023
Sony	XL-2100U, A, E [A1606-034B]	RP-P022

Sony	XL-2200U, A, E [A1085-447A]	RP-P022-1
Sony	XL-2300, A, E	RP-P022
Sony	XL2400U	RP-E19.8
Sony	XL2500U	RP-E19.8
Sony	XL5000	RP-P022-3
Sony	XL-5100U, A, E	RP-P022
Sony	XL-5200U, A, E	RP-P022
Sony	XL-5300	RP-P022-2
Toshiba	72782309	RP-E023
Toshiba	TBL4-LMP	RP-E023
Toshiba	D42-LMP/72620067	RP-TOS
Toshiba	D95-LMP / 231153A / LV-672	RP-TOS
Toshiba	TB25-LMP / 23311083 / 23587201	RP-TOS
Toshiba	Y66-LMP / Y67-LMP / 75007110 / 75007091 / 75008204 / 72514011	RP-TOS
Toshiba	Y196-LMP / 75007111 / 72514012X	RP-TOS
Viore	IPT46DLP30 (46" DLP TV lamp)	RP-E023
Vivitek	379755220	RP-E023
Vivitek	3797048800	RP-E023
Vivitek	3797631900-S	RP-E023
Vivitek	RP42HD51A	RP-TOS (SHP-87)
Vizio	For TV Model: RP-56	RP-E023
Zenith	3110V0139B	RP-P022
Zenith	6912B22001A	RP-E022-1
Zenith	6912B22002C	RP-E023
Zenith	6912B22010A	RP-E022-3
Zenith	6912B22007A	RP-E023
Zenith	6912B22007B	RP-E022
Zenith	6912B22010	RP-E022-3
Zenith	6912V00006C	RP-P022